





FIG.3













1914 — KcommandCapability item="delete">false</commandCapability> 1912 — /commandCapability item="copy">true/commandCapability>
1913 — /commandCapability item="move">false/commandCapability>

101



OBLON, SPIVAK, ET AL DOCKET #: 251215US2 INV: Takaya MATSUISHI SHEET <u>10</u> OF <u>30</u>

FIG.10







FIG.12









FIG.14







```
<commandCapability item="copy">true</commandCapability>
<commandCapability item="move">true</commandCapability>
<commandCapability item="delete">true</commandCapability></commandCapability item="delete">true</commandCapability></commandCapability</commandCapability>
cprofile user="userC">
```










FIG.19

















```
3913 — CommandCapability item="fax">true</commandCapability> 3914 — CommandCapability item="deliver">false</commandCapability>
                                          3912 — <commandCapability item="print">true</commandCapability>
cprofile user="userD">
```

















FIG.29

